

### Discontinuation Notice of SOBA for Factory.

#### Product Discontinuation

SOBA for FACTORY

#### Recommended Replacement

---



**Model SOBA Series**



**No recommended replacement**

#### [ Discontinuation date ]

The end of April 2013

#### [ Product Discontinuation and recommended replacement ]

Product discontinuation	Recommended replacement
4AA04-S4F10-V01	No recommended replacement
4AA04-S4F11-L02	
4AA04-S4F11-L03	
4AA04-S4F11-L04	
4AA04-S4F11-L52	
4AA04-S4F11-P01	
4AA04-S4F11-P02	
4AA04-S4F11-P11	
4AA04-S4F11-P51	
4AA04-S4F11-P52	
4AA04-S4F11-P99	
4AA04-S4F11-S01	
4AA04-S4F11-S50	
VP-S4F-GU-CHN-12	
VP-S4F-GW-12	
VP-S4F-GWR-12	
VP-S4F-GWR-CHN-12	
VP-S4F-GWR-IND-12	
VP-S4F-L	
VP-S4F-L-ADD	
VP-S4F-L-ADD-C	
VP-S4F-L-C	
VP-S4F-SK-12	
VP-S4F-SK-CHN-12	
VP-S4F-SK-IND-12	
VP-S4F-SVC-12	
VP-S4F-VU-12	
VP-S4F-VU-CHN-12	

Specifications and prices in this product news are as of the issue date and are subject to change without notice.  
Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.